# Oil Field Environmental Incident Summary

**Responsible Party:** OXY USA INC. **Well Operator:** OXY USA INC.

Well Name: STATE TITOS 1-3-10H-142-98

Field Name: SADDLE BUTTE Well File #: 21395

Date Incident:1/26/2016Time Incident:11:00Facility ID Number:County:BILLINGSTwp:143Rng:98Sec:34Qtr:

Location Description:

Submitted By: Robyn Espinoza Received By:

Contact Person: Robyn Espinoza

PO BOX 2000

DICKINSON, ND 58601

General Land Use: Well/Facility Site

Affected Medium: Topsoil

**Distance Nearest Occupied Building:** 

Distance Nearest Water Well:

Type of Incident: Equipment Failure

Release Contained in Dike: No Reported to NRC: No

Spilled Units Recovered Units Followup Units
20 Gallons 20 Gallons 20 gallons

Brine Other

Oil

**Description of Other Released Contaminant:** 

Inspected: Written Report Received: 1/26/2016 Clean Up Concluded: 1/26/2016

Risk Evaluation:

Contaminated surface material

Areal Extent:

Adjacent land 100 ft X 30 ft

## Potential Environmental Impacts:

Contaminated surface material

### Action Taken or Planned:

The well was shut in to prevent further release, SM Fencing was immediately dispatched to recover all oil misted snow and to remove any other materials as needed.

Wastes Disposal Location: Chimney Butte

Agencies Involved:

### **Updates**

Date: 1/26/2016 Status: Reviewed - Follow-up Required Author: Crowdus, Kory

**Updated Oil Volume:** 

**Updated Salt Water Volume:** 

**Updated Other Volume:** 

**Updated Other Contaminant** 

Notes:

Release impacted area off location. Follow-up is required.

Date: 2/2/2016 Status: Inspection Author: O'Gorman, Brian

**Updated Oil Volume:** 

**Updated Salt Water Volume:** 

**Updated Other Volume:** 

**Updated Other Contaminant** 

## Notes:

Arrived on location at 10:15. 23 degrees F, mostly sunny, NE wind 0-10 mph. Walked the perimeter of the well pad and took photos. It appeared that the release occurred near the SE corner of the well pad where an area approximately 100' by 30' had been scraped. The area was free of snow and lacked dormant vegetation. Did not observe any indications of petroleum impacts to the scraped area or other areas around the pad. No further followup needed at this time.